5-18588

TOP SCORET

PHOTOGRAPHIC INTERPRETATION REPORT



ICBM COMPLEX, PERM, USSR PROBABLE LAUNCH SITE GI3

Declass Review by NIMA/DOD

TCS-80907/65 COPY 4 1 PAGE

JULY 1965

handle via TALENT-KEYHOLE control only

GROUP I EXCLUDED FROM AUTOMATIC DOWNGRADING AND DECLASSIFICATION

TOP CEONET

TOP SECRET RUFF

Handle Via TALENT-KEYHOLE Control System Only

TCS-80907/65 July 1965

NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER

(C)

Perm ICBM Complex, Probable Launch Site G13*

GEO COORDINATES

NPIC NO

COMOR NO

USSR

57-41N 056-15E

0156 None

16L9

None

REFERENCES

25X1D

Location: 1.8 nm West of the Complex Support Facility 25X1D

Type: IIID


Negation Date:

Stage of Construction: Undetermined

Date First Seen

This newly identified site contains a probable characteristic graded earthen silo access. The access is parallel to those at the other single-silo sites at this complex. A clearing for a road leads from the complex main road to the site. Poor quality, non-stereo photography precludes additional details.

*Tentative group/site designator.



Handle Via TALENT-KEYHOLE Control System Only